


**AMPCO Parking Lot  
Soil Sample Location Map**  
 Vermiculite Intermountain Facility  
 Libby Sister Site SLC2  
 Salt Lake City, UT

**Legend**

- Approximate Subsample Location
- Approximate Sampling Grid Location
- Building Outline
- Site Boundary
- Approximate Boundary of Former Processing Building



**CDM**




AMPCO PARKING LOT SOIL RESULTS			
Grid	Fill Material	Native 1	Native 2
1	ND 0 - 38"	ND 38" - 44"	ND 44" - 50"
2	ND 0 - 15"	ND 15" - 21"	ND 21" - 27"
3	ND 0 - 13"	ND 13" - 19"	ND 19" - 25"
4	ND 0 - 34"	ND 34" - 40"	ND 40" - 46"
5	Tr 0 - 28"	ND 28" - 34"	ND 34" - 40"
6	ND 0 - 25"	ND 25" - 31"	ND 31" - 37"
7	Tr 0 - 31"	ND 31" - 37"	Tr 37" - 43"

Depths (inches) are approximate below ground surface  
 Soil samples analyzed by PLM (NIOSH 9002)  
 Native 1 Native layer approximately 0 to 6 inches below fill material  
 Native 2 Native layer approximately 6 to 12 inches below fill material  
 inches  
 ND Nondefect  
 Tr Trace (< 0.2%) Libby Amphibole Asbestos

**AMPCO Parking Lot  
Soil Sample Location Map**  
 Vermiculite Intermountain Facility  
 Libby Sister Site SLC2  
 Salt Lake City, UT

**Legend**

- Approximate Subsample Location
- Approximate Sampling Grid Location
- Building Outline
- Site Boundary
- Approximate Boundary of Former Processing Building



**CDM**